## WATERWATCH Corangamite Communities Caring for Catchments

## Waterwatch Data Record Sheet

Monitor

			The second secon	
Date and time:	18017	Site C	ode:	
	10.8.0	10:45 arc 0-	THO 114	
Waterway and location:				
THOMP.	SON CREEK	@ DAUS	RESERVE	
Site Risk Assessment completed – yes / no				
Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)				

Parameter	Results
рН	7 5
(pH units)	
Electrical conductivity	58 MS = 5,800 MS.
(record as μS/cm)	(Write units displayed on meter. If needed multiply by 1,000 to convert mS to $\mu$ S)
Turbidity	
(NTUs)	
Reactive phosphorus	
(mgP/I)	0.06

10			
Photos of monitoring site taken upstream, across stream and downstream?			
These photos, with a heading to identify the sitecode, c deirdre.murphy@ccma.vic.gov.au.	an be sent as an MMS to 0418145818 or emailed to		
Additional observations eg what birds, plants, frogs are present?			
Record amount of litter	Record amount of illegal dumping		
Rating 1 to 5	Rating 1 to 5  Do you need to take a photo and report to EPA?		