WATERWATCH Corangamite Communities Caring for Catchments

Waterwatch Data Record Sheet

Monitor P Syme

Date and time:	Site Code:		
8/08/17 1030	(0-60-20		
Waterway and location:			
PEACOCK AVE			
CONIS CRK			
Site Risk Assessment completed - yes I no			
Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)			

Parameter	Results
*	
рН	Seeming
(pH units)	1,5
Electrical conductivity	1772
(record as μS/cm)	(Write units displayed on meter. If needed multiply by 1,000 to convert mS to μ S)
Turbidity	1.
(NTUs)	210
Reactive phosphorus	
(mgP/I)	0'06

Photos of monitoring site taken upstream, across stream and downstream?			
These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to deirdre.murphy@ccma.vic.gov.au .			
Additional observations eg what birds, plants, frogs are present?			
SHOPPING TROLLEY & SIGN IN	us ter		
NO LIFE PRESENT			
Record amount of litter	Record amount of illegal dumping		
Rating 1 to 5	Rating 1 to 5		
	Do you need to take a photo and report to EPA?		