WATERWATCH Corangamite

Waterwatch Data Record Sheet

Monitor PSyme

			0	communities caring for calcinnents	
Date and time:	1			Site Code:	
	18.8.17	llan		MO-M00090	
Waterway and location:					
Marsolo	Moorabool	River,	Fyar	rsford	
Site Risk Assessment completed – ves/ no					

Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)

Parameter	Results
рН	
(pH units)	7.5
Electrical conductivity	3.76 ms/cm 3760 ms
(record as μS/cm)	(Write units displayed on meter. If needed multiply by 1,000 to convert mS to μ S)
Turbidity	
(NTUs)	17.5
Reactive phosphorus	
(mgP/I)	0.012

Photos of monitoring site taken upstream, across stream and downstream?

These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to deirdre.murphy@ccma.vic.gov.au.

Additional observations eg what birds, plants, frogs are present?

Mance - less wildlife f plants
- pead frees
- Some birds not many frog Record amount of illegal dumping

Rating 1 to 5

Do you need to take a photo and report to EPA?