

Entered 15/2/2017 *Maffei*

96-19750

West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

RECEIVED  
21 DEC 2015  
BY:

**Site Details**

Site Code: *TYR 090*

Site Name:

Site Grid Reference Easting:  
Northing:

**Test Details**

Date: *21 Dec 2015*

Time: *9:51*  AM  PM

Person(s) Conducting the Survey / Test: *Peter Maffei*

Name of Monitoring Group: *FOTP*

Your Meter - Reading Before Calibration (when in CAL Mode)				Your Meter - Reading Post Calibration (after pressing the ENT button)			
EC Meter	<i>1380</i>	pH Meter in 4.01	<i>4.1</i>	EC Meter	<i>1410</i>	pH Meter in 4.01	<i>4.0</i>
pH Meter in 7.01	<i>7.6</i>			pH Meter in 7.01	<i>7.0</i>		

**Water Condition (Circle)**

Steady Flow     Rising     Peak     Falling *slightly*     Stagnant (pools)     Dry (no water)

**Test Results**

Air Temperature	<i>19.3</i>	°C
Water Temperature	<i>23.0</i>	°C
pH	<i>5.7</i>	
Electrical Conductivity	<i>80</i>	<input checked="" type="checkbox"/> µS <input type="checkbox"/> mS
Reactive Phosphorus	<i>0.015</i>	mg/L P
Turbidity	<i>&lt;10</i>	N.T.U.
Dissolved Oxygen:	<i>N.T.</i>	<input type="checkbox"/> mg/L <input type="checkbox"/> %

**Any Comments for Your Facilitator?**

**Weather Conditions at Time of Sampling**

Sunny     Cloudy

Overcast     Raining

Windy

**Water Appearance**

Clear     Muddy

Milky     Foamy / Frothy

Stained Green     Stained Brown

Smelly     Scummy

Oily     Other:

**Last Rainfall**

More than a week ago     During the last week

During the last 24 hours     Raining Now

Amount of rain: *< 2.0* mm

**Drains**

Drain Flow:  Drain flowing     Drain not flowing