Strawate a concurr

Waterwatch Melbourne Physical and Chemical Analysis

Monitorina	site	details
540 6 B R R H H G O H B 7 8 7 7 1	ليدة كالماليين	Contract Contract to the contr

ME-ETA 900 Site code:

Site description: TARAGO RIVER @ ROBIN HOOD RESERVE
Name of monitoring group FISHER ROAD, DROWN WEST

Persons monitoring: JEFF SMYTHE Date and time of monitoring:

25/3/2017 10-30 am.

Please record your data below:

Please record your data belo		
्राप्तः । श्रेटब्रोह्न सम्बद्धाः । स्टब्स्	Complete Control (Control (Con	(Colympic County)
Ak Lombergials Talamasanan	23 "5	The state of the s
Water Temperature	21 "	the control of the second control of the sec
Turbidity	< 10 MISS	
pH	NO READING CHIEF.	
Conductivity	210 10 5 / 1379	The state of the s
Dissolved Oxygen	882 / C	% Saturation
Pirospirate (If using Lamotte Smart2 Colorimeter multiply by 0.326 to calculate mg/L)	0.02 190:/1	
Ammonium	Marke / L	the second section is the second of the second second second section in the second second second second second
Hitrate	my / L	

Observations and Notes:


What has changed since last time you monitored?

What stands out about the site today?

Other observations:







Waterway Information								
Rate of flow: Very fast None If 'Other', please spe	☐ Fast ☐ Permanent ecify:	☐ Normal ba		•	Trickle			
Type of flow: ☐ Rising ☐ Sto If 'Other', please spo		☐ Peak	□ Dry □ Pools	s / Puddles	□ Other			
Waterway Apped ☑ Clear ☑ Olly If 'Other', please spe	☐ Muddy ☐ Discoloured	☐ Smelly ☐ Milky	☐ Frothy ☐ Stained		Scummy Other			
Waterway depth: <u>35</u> cm (0 to 3000cm) Waterway width:								
Weather: □ Sunny □ Hall If 'Other', please spo	☐ Cloudy ☐ Windy ecify:	Overcast Groggy	☐ Showers ☐ Other		Rain .			
Last rainfall: Raining now	🗆 Last 24hrs	🗖 Last 3 days	🗆 Last 7 days	☑ More th	an a week ago			
Litter / Pollutan Cans Food Packets Waxed Cardboar		Paper Plastic Bottles	Clothing Polystyrene Petrol/Diesel (m	Oil (Car ²) Otho				



