

Waterwatch Data Record Sheet

Monitor
P Syme



Date and time: 18/AUG/2017 11am	Site Code: CO_BARBOO
Waterway and location: MIDBARWON WINCH	
Site Risk Assessment completed <input checked="" type="radio"/> yes / no	
Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)	

Parameter	Results
pH (pH units)	7.5
Electrical conductivity (record as $\mu\text{S}/\text{cm}$)	1084 $\mu\text{S}/\text{cm}$ (Write units displayed on meter. If needed multiply by 1,000 to convert mS to μS)
Turbidity (NTUs)	20-30 NTU (25 NTU)
Reactive phosphorus (mgP/l)	0.06

Photos of monitoring site taken upstream, across stream and downstream? These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to deirdre.murphy@ccma.vic.gov.au .	
Additional observations eg what birds, plants, frogs are present? 2 GEESE DUCKS NO FROGS OR FROG NOISE 3 WILLY WAG TAIL COCKATOOS. LOTS OF BIRD NOISE.	
Record amount of litter Rating 1 to 5 1.5 NO LITTER SMALL AMOUNT	Record amount of illegal dumping Rating 1 to 5 1 Do you need to take a photo and report to EPA? NO DUMPING BOAT CONSISTENT W/TH ORIGINAL PHOTO