Corangamite

Waterwatch Data Record Sheet

Date and time:

Monstor P Syme

Site Code:

17 10:30am

Communities Caring for Catchments

Waterway and location. CO _BARO / O		
Barwon River Inverteigh		
Site Risk Assessment completed – yes / no		
Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)		
Parameter	Results	
pH	7.0	
(pH units)	7.0	•
Electrical conductivity	2-7.7 mS/	m 3 = 2,270 MS/C
(record as μS/cm)	(Write units displayed on meter. If needed multiply by 1,000 to convert mS to μ S)	
Turbidity	HM 20	
(NTUs)		
Reactive phosphorus		, , ,
(mgP/I)	0.03	
Photos of monitoring site taken upstream, across stream and downstream?		
These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to deirdre.murphy@ccma.vic.gov.au .		
Additional observations eg what birds, plants, frogs are present?		
Record amount of litter		Record amount of illegal dumping
Rating 1 to 5		Rating 1 to 5
_		Do you need to take a photo and report to EPA?