



Waterwatch Data Record Sheet

Monitor P Syme

Communities Caring for Catchments

Date and time: <i>18.08.17</i> <i>11:00</i>	Site Code: <i>CO-COW015</i>
Waterway and location: <i>COVIES CREE NEAR DEPOT</i>	
Site Risk Assessment completed <input checked="" type="checkbox"/> yes <input type="checkbox"/> no	
Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)	

Parameter	Results
pH (pH units)	<i>8</i>
Electrical conductivity (record as $\mu\text{S}/\text{cm}$)	<i>4760</i> <small>(Write units displayed on meter. If needed multiply by 1,000 to convert mS to μS)</small>
Turbidity (NTUs)	<i><10</i>
Reactive phosphorus (mgP/l)	<i>0.03</i>

Photos of monitoring site taken upstream, across stream and downstream? These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to deirdre.murphy@ccma.vic.gov.au .	
Additional observations eg what birds, plants, frogs are present? <i>LOTS OF NATIVE PLANTS, LOTS OF FROGS, 8x DUCKS (2 varieties)</i>	
Record amount of litter Rating 1 to 5 <i>2</i>	Record amount of illegal dumping Rating 1 to 5 <i>1</i> <i>Do you need to take a photo and report to EPA?</i>