

Waterwatch Data Record Sheet

*Monitor
P. Syme*



Date and time: <i>18.8.17 10:00</i>	Site Code: <i>site 8 Hovells HOV025</i>
Waterway and location: <i>Under BRIDGE</i>	
Site Risk Assessment completed – <input checked="" type="radio"/> yes / <input type="radio"/> no <i>No.</i>	
Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)	

Parameter	Results
	<i>UNDER BRIDGE</i>
pH (pH units)	<i>8</i>
Electrical conductivity (record as $\mu\text{S}/\text{cm}$)	<i>2.88 MS/CM</i> <small>(Write units displayed on meter. If needed multiply by 1,000 to convert mS to μS)</small>
Turbidity (NTUs)	<i>20</i>
Reactive phosphorus (mgP/l)	<i>0.03</i>

Photos of monitoring site taken upstream, across stream and downstream? These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to deirdre.murphy@ccma.vic.gov.au .	
Additional observations eg what birds, plants, frogs are present? <i>No Animals MUDLARK - DEAD 2 DUCKS WATERFOWL</i>	
Record amount of litter Rating 1 to 5 <i>1</i>	Record amount of illegal dumping Rating 1 to 5 <i>NONE</i> <i>Do you need to take a photo and report to EPA?</i>