Monitor PSyme



Waterwatch Data Record Sheet

Date and time: 8 8 17 9 30 Site Code: CO_LET 030

Waterway and location: Inverteigh

Site Risk Assessment completed—ves no

Are there any incidents or near misses to report? — (if yes, please let Deirdre or Warren know)

Parameter	Results
arameter	I NESUILS
рН	
Time the state of	1.0
(pH units)	
	A A
Electrical conductivity	136165 (1)
(record as μS/cm)	(Write units displayed on meter. If needed multiply by 1,000 to convert mS to μ S)
Turbidity	125
(NTUs)	
Reactive phosphorus	13/10/1
(- 5/1)	0.06
(mgP/I)	173/8
<u> </u>	· // •

Photos of monitoring site taken upstream, across stream and downstream?			
These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to deirdre.murphy@ccma.vic.gov.au .			
Additional observations eg what birds, plants, frogs are present?			
Additional observations eg what birds, plants, frogs are present? Yellow bellg bird - with mowhatk			
Record amount of litter	Record amount of illegal dumping		
Rating 1 to 5	Rating 1 to 5		
	Do you need to take a photo and report to EPA?		