



**Waterwatch Data Record Sheet**

*Monitor  
P Syme.*

Date and time: <i>18.8.17 10:00am</i>	Site Code: <i>CO-T140110</i>
Waterway and location: <i>① THOMPSON</i>	
Site Risk Assessment completed <input checked="" type="checkbox"/> yes / no	
Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)	

Parameter	Results
pH (pH units)	<i>7.5</i>
Electrical conductivity (record as $\mu\text{S}/\text{cm}$ )	<i>6.24 mS = 6,240 <math>\mu\text{S}</math>.</i> <small>(Write units displayed on meter. If needed multiply by 1,000 to convert mS to <math>\mu\text{S}</math>)</small>
Turbidity (NTUs)	<i>&lt; 10</i>
Reactive phosphorus (mgP/l)	<i>0.045</i>

Photos of monitoring site taken upstream, across stream and downstream?  These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to <a href="mailto:deirdre.murphy@ccma.vic.gov.au">deirdre.murphy@ccma.vic.gov.au</a> .	
Additional observations eg what birds, plants, frogs are present?  <i>2x WHITE IBIS? 1x BLACK SWAN FLOWERS (ANDIBEE)</i>	
Record amount of litter  Rating 1 to 5	Record amount of illegal dumping  Rating 1 to 5  Do you need to take a photo and report to EPA?