

Waterwatch Data Record Sheet

Monitor
P Syme



Date and time: 18/8/17 10:00	Site Code: CO BAR 087
Waterway and location: Merrawarr rd, Barwon River	
Site Risk Assessment completed <input checked="" type="radio"/> yes / no	
Are there any incidents or near misses to report? – (if yes, please let Deirdre or Warren know)	

Parameter	Results
pH (pH units)	6.5
Electrical conductivity (record as $\mu\text{S}/\text{cm}$)	166.8 1668 μS (Write units displayed on meter. If needed multiply by 1,000 to convert mS to μS)
Turbidity (NTUs)	< 20 15
Reactive phosphorus (mgP/l)	0.045

Photos of monitoring site taken upstream, across stream and downstream? These photos, with a heading to identify the sitecode, can be sent as an MMS to 0418145818 or emailed to deirdre.murphy@ccma.vic.gov.au .	
Additional observations eg what birds, plants, frogs are present? Honey eaters, fidges, wrens, pigeons	
Record amount of litter Rating 1 to 5 4	Record amount of illegal dumping Rating 1 to 5 4 Do you need to take a photo and report to EPA?