

Waterwatch Results: Friends of Dandenong Valley Parklands Dandenong Creek and Blind Creek

Test Completed Date: 27/10/2017 24/11/2017

Tests completed by: Christine Dix, Chris Miller, David Lumb, Bryan Lott, Rex Fuller

Test Site	Dandenong Creek Bridge site (DDN 050)	Blind Creek (DBC 250)
Time:	10:20 am	10:30 am
Ammonium mg/l	1053 0.20	11.17 0.07
D.O (Dissolved oxygen concentration)	2.2	4.0 44.86%
Water Temperature	20.8	20.7
Air Temperature	23.7	24.7
pH (Acidity/alkalinity)	7.0	7.2
Electrical Conductivity	970	1900
Reactive Phosphate (Nutrient levels)	102 0.10	11.11 0.20
Turbidity	20	80

Site Descriptions	Dandenong Creek Bridge site (DDN 050)	Blind Creek (DBC 250)
Weather (Sunny, cloudy, overcast, raining, windy)	overcast sprinkle of rain	overcast
Rainfall (More than a week ago, during last week, during last 24 hours, raining now)	last 24 hrs	last 24 hrs
Amount of rainfall	14.5mm during the week 1.2mm	14.5mm during the week 1.2mm
Water flow (Flood, Medium, Low)	low	Low
Water appearance (Clear, muddy, milky, other)	muddy with pollution	
Stream depth (0-50cm, 51-99cm, 1-2m, >2m)	0-50cm	>50
Stream width (<2m, 2m-5m, >5m)	>5m	3-5m
Litter/pollutants (bottles, plastic, packets, waxed cardboard, cans, polystyrene, paper, clothing)	none	none

Comments: * in stream yellowish bubbles, slight shower

Blind Ck - deep water, oil streak on top on path
no flow in Blind Ck - more weed in creek.