

Waterwatch Results: Friends of Dandenong Valley Parklands Dandenong Creek and Blind Creek

Test Completed Date: 25/5/2018

Tests completed by: Christine Dix,

Test Site	Dandenong Creek Bridge site (DDN 050)	Blind Creek (DBC 250)
Time: 10:30	10:30	10:50
Ammonium mg/l	11.5 0.10	11.2 0.02
D.O (Dissolved oxygen concentration)	8.0 73.27 ^g	8.0 73.27 ^g
Water Temperature	12.2	11.4
Air Temperature	12.8	11.9
pH (Acidity/alkalinity)	6.9	11.4 7.2
Electrical Conductivity	300	200
Reactive Phosphate (Nutrient levels)	11.2 0.10	12.0 0.07
Turbidity	30	30

Site Descriptions	Dandenong Creek Bridge site (DDN 050)	Blind Creek (DBC 250)
Weather (Sunny, cloudy, overcast, raining, windy)	Sunny clear	Sunny
Rainfall (More than a week ago, during last week, during last 24 hours, raining now)	During the week	during the week
Amount of rainfall	10 mm.	10 mm
Water flow (Flood, Medium, Low)	Med.	Med
Water appearance (Clear, muddy, milky, other)	Muddy	Clear
Stream depth (0-50cm, 51-99cm, 1-2m, >2m)	0.5-99cm)	0-50cm
Stream width (<2m, 2m-5m, >5m)	>5m.	2-5m
Litter/pollutants (bottles, plastic, packets, waxed cardboard, cans, polystyrene, paper, clothing)	Plastic, Paper Alum Can, Ball - High level up Bank	nil

Comments:

.....

.....

.....

.....