

Waterwatch Results: Friends of Dandenong Valley Parklands Dandenong Creek and Blind Creek

Tests completed by:

Test Completed	Dandenong Creek	Blind Creek
Date:	Bridge site (DDN 050)	(DBC 250) ME_DJE 200
Time:		11-05
Ammonium mg/l		0.07
D.O (Dissolved oxygen concentration)		9.6 91.78%
Electrical Conductivity		220
pH (Acidity/alkalinity)		7.3
Reactive Phosphate (Nutrient levels)		0.25
Air Temperature		12.8
Water Temperature		13.3
Turbidity		15

Site Descriptions	Dandenong Creek	Blind Creek
	Bridge site (DDN 050)	(DBC 250)
Weather (Sunny, cloudy, overcast, raining, windy)		cloudy
Rainfall (More than a week, during last week, last 24 hours, raining now)		6mm last 24hrs
Amount of rainfall		6mm
Water flow (Flood, Medium, Low)		N/A
Water appearance (Clear, muddy, milky, other)		muddy
Stream depth (0-50cm, 51-100cm, 1-2m, >2m)		0-50 cm
Stream width (3-5m, >5m)		N/A.
Litter/pollutants		none