

# Waterwatch Results: Friends of Dandenong Valley Parklands Dandenong Creek and Jells Lake Landing

Test Completed Date: 25/10/19

Tests completed by: CD, DL, JM

Test Site	Calibration *	Dandenong Creek Bridge site (DDN 050)	Jells Lake Landing (ME_DJE 200)
Time:		10:15	10:30
Ammonium mg/l		<del>0.0</del> 0.0	<del>0.0</del> 0.0
D.O (Dissolved oxygen concentration)		6.5 67.79%	9.5 102.69%
Water Temperature		<del>17.3</del> 17.3	19.1
Air Temperature		15.1	14.1
*pH (Acidity/alkalinity)	E	7.4	8.6
*Electrical Conductivity	C	550	230
Reactive Phosphate (Nutrient levels)		0.07	0.02
Turbidity		10	20

Site Descriptions	Dandenong Creek Bridge site (DDN 050)	Jells Lake Landing (ME_DJE 200)
Weather (Sunny, cloudy, overcast, raining, windy)	OVERCAST	raining
Rainfall (More than a week ago, during last week, during last 24 hours, raining now)	LIGHT RAINY TODAY SOME THUNDER	" NOW
Amount of rainfall		
Water flow (Flood, Medium, Low)	med	N/A
Water appearance (Clear, muddy, milky, other)	clear	clear
Stream depth (0-50cm, 51-99cm, 1-2m, >2m)	0-50cm	0-50cm
Stream width (<2m, 2m-5m, >5m)	>5m	N/A.
Litter/pollutants (bottles, plastic, packets, waxed cardboard, cans, polystyrene, paper, clothing)	silver paper in water	—

Comments: .....

.....

.....

.....

.....