

Waterwatch Results: Friends of Dandenong Valley Parklands Dandenong Creek and Blind Creek

Tests completed by: *Christine Dix, John Dix*

Test Completed Date:	Dandenong Creek Bridge site (DDN 050)	Blind Creek Wells Lake (DBC 250)
15/11/19		
Time:	10.40	10.55
Ammonium mg/l	0.00	0.00
D.O (Dissolved oxygen concentration)	7.0 70%	7.0 7.8
Electrical Conductivity	480	240
pH (Acidity/alkalinity)	7.7	7.5
Reactive Phosphate (Nutrient levels)	0.10	0.03
Air Temperature	14.5	13.6
Water Temperature	15.4	16.7
Turbidity	15	15

Site Descriptions	Dandenong Creek Bridge site (DDN 050)	Blind Creek Wells Lake (DBC 250)
Weather (Sunny, cloudy, overcast, raining, windy)	overcast	overcast
Rainfall (More than a week, <u>during last week</u> , last 24 hours, raining now)	37.4mm	11
Amount of rainfall		37.4
Water flow (Flood, Medium, Low)	Med	N/A
Water appearance (Clear, muddy, milky, other)	Clear	Cloudy
Stream depth (0-50cm, 51-100cm, 1-2m, >2m)	0-50	0-50
Stream width (3-5m, >5m)	>5m	N/A
Litter/pollutants	nil	-