West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details			Test Deta	ils				
Site Code: HAZ 017 Site Name: Hazel CK at Ascott 5 Site Grid Reference Easting: 406187			Date: 16	. 1	10 DAM OP		19 MAY 2010	
Site Name: Hazel CK at Ascott &			Time:	10	10 DAM DPM	Л		
Site Grid Reference Easting: 406187			Person(s) Conducting the Survey / Test: DAVID					
Nort		Name of Mo	nitor	ing Group: Warragul	<u>_ L</u>	andcave		
Test Results			Weather Conditions	20.52.08.52				
Air Temperature	15	°C			Sunny		☐ Cloudy	
Water Temperature	11-3	°C			☐ Overcast		Raining	
рН	5.9				☐ Windy			
Electrical Conductivity	230	□µS □mS						
Reactive Phosphorus	0.09	mg/L P			Last Rainfall	- A 6		
Turbidity	9	N.T.U.			☐ More than a week ago	Ε	During the last week	
Dissolved Oxygen:	<u> </u>	mg/	L .		☑ During the last 24 hours	[☐ Raining Now	
Nitrates		mg/L NO₃			Amount of rain:	8	mm	
Stream Flow		litre	s/sec					
					Water Flow			
Deepest Part of Stream (estimate only)					☐ Not flowing	E	☑ Slow	
☐ Up to 50cm ☐ Up to 1m ☐ Up to 2m					☐ Fast		☐ Rapid	
☐ Up to 5m ☐ Over 5m ☐ Unknown					☐ Temporary	☐ Permanent		
Average width of stream: cm								
					Water Appearance			
Drains					Clear		☐ Muddy	
Drain Flow: ☐ Drain flowing ☐ Drain not flowing					☐ Milky	[☐ Foamy / Frothy	
Description of drain water: Colour:					☐ Stained Green	[Stained Brown	
Odour:					☐ Smelly		Scummy	
Any Comments for Your Facilitator?					Oily		☐ Other:	
Any Comments for Four Facilitator:								
					Litter Pollutants (tick	typ	e found)	
					☐ Paper	[] Plastic	
			·		☐ Bottles	[☐ Cans	
					☐ Packets	Ε	☐ Polystyrene	
					☐ Car bodies	[Petrol / diesel	
					☐ Clothing		☐ Waxed cardboard	
					☐ Other			

Your Mete	r - Pre Calibration Reading	Your Meter - Post Calibration Reading
EC Meter	1380	EC Meter V430
pH Meter in 7.01	7.8 pH Meter in (NA Hanna) 4-2	pH Meter in 7.01 pH Meter in 4.01