Water Quality Monitoring Data Sheet

Site Details			Test Det	tails			
Site Code: HAZO15			Date: 02	04/10 · ((dd/mm/yyyy)		
Site Name: KING STREET			Time:	.00	🗙 АМ 🗌 РМ		
Site Grid Reference Easting:			Person(s)	Person(s) Conducting the Survey / Test: Kake Britton.			
Northing:			Name of M	Name of Monitoring Group:			
Your Meter -	Reading Pre	Calibration		Your Meter	- Reading Post	Calibration	
(when in CA					ing the ENT Bu		
EC Meter pH Meter in pH Meter in			·	EC Meter			
pH Meter in 4.01				pH Meter in 4.01		bH Meter in 7.01	
Water Flows	Conditions		-				
Steady Flow	🗌 Rising		Peak	Falling	🗌 Stagnant	(pool) Dry (No Water)	1
Test Results	3			Weat	her Conditions	at Time of Sampling	
Air Tempe		°C		🗌 Sun		Cloudy	
Water Tempe	erature: 17.7	°C		⊠ k Ove	rcast	Raining	
Electrical Condu	uctivity: 320	🗌 µS	🗌 mS	🗌 🗌 Win	dy		
	рн: 6.5		I	L	,, <u>, , , , , , , , , , , , , , , , , ,</u>		
Tu	ırbidity: 8	N.T.U.		Last	Rainfall		
Reactive Phosphorus: (). 07 mg/L P				🗌 Mor	e than a week ago	🔀 During the last week	
Gauge Board Depth:				🗋 Duri	ing the last 24 hours	Raining Now	
Dissolved C	xygen:	🔲 mg/L	🗌 % Saturation	Amoun	t of rain:	mm	
Litter Polluta	ants (tick type	found)	Wate	Appearance			
Paper Plastic				🔀 Clea	ar	☐ Muddy	
Bottles		Cans		Milk	у	E Foamy / Frothy	
A Packets			e	Stai	ned Green	X Stained Brown	
Car bodies Petrol / diesel			esel	Sme	elly	Scummy	
Clothing Other STEE		FEEL .	🗌 Oily		Other:		
Drains			Any	Comments for Y	our Facilitator?		
Drain Flow:	Drain flowing	🗌 Drain not f	lowing				