

HUC001

RECEIVED
07 FEB 2012

West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details

Site Code: HWC-4

Site Name: WETLANDS LAKE

Site Grid Reference Easting: _____
Northing: _____

Test Details

BY: _____

Date: 22-1-12 + 3-1-12

Time: 1200 AM PM

Person(s) Conducting the Survey / Test: PETE REP.

Name of Monitoring Group: HEYFIELD

Your Meter - Reading Before Calibration (when in CAL Mode)				Your Meter - Reading Post Calibration (after pressing the ENT button)			
EC Meter	<u>1370</u>			EC Meter	<u>1420</u>		
pH Meter in 7.01	<u>7.3</u>	pH Meter in 4.01	<u>7.0</u>	pH Meter in 7.01	<u>7.0</u>	pH Meter in 4.01	<u>4.0</u>

Drains

Drain Flow: Drain flowing Drain not flowing

Test Results

Air Temperature	<u>22-7</u>	°C
Water Temperature	<u>22-3</u>	°C
pH	<u>7.5</u>	
Electrical Conductivity	<u>1980</u>	<input type="checkbox"/> μS <input type="checkbox"/> mS
Reactive Phosphorus	<u>-</u>	mg/L P
Turbidity	<u>25</u>	N.T.U.

Bud
REP
4
7.2
1680
0.70
26

Any Comments for Your Facilitator?

2 TEST ON LAKE!

Weather Conditions at Time of Sampling

Sunny Cloudy

Overcast Raining

Windy

Water Appearance

Clear Muddy

Milky Foamy / Frothy

Stained Green Stained Brown

Smelly Scummy

Oily Other:

Last Rainfall

More than a week ago During the last week

During the last 24 hours Raining Now

Amount of rain: _____ mm