West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details

Site Code: **LAT021**

Site Name: **Latrobe River @ Scarnes Bridge**

Site Grid Reference   Easting:

Northing:

Test Details

Date: 1·5·2010

Time: 11·55   ☑AM   ☐ PM

Person(s) Conducting the Survey / Test: Judy

Name of Monitoring Group:

Your Meter - Reading Before Calibration (when in CAL Mode)				Your Meter - Reading Post Calibration (after pressing the ENT button)			
EC Meter	As per Wades creek			EC Meter			
pH Meter in 7.01		pH Meter in 4.01		pH Meter in 7.01		pH Meter in 4.01	

Water Condition (Circle)

Steady Flow	Rising	Peak	Falling	Stagnant (pools)	Dry (no water)
(Steady Flow)					

Test Results

Air Temperature	16·5	°C
Water Temperature	14·7	°C
pH	7·0	
Electrical Conductivity	390	☑ µS ☐ mS
Reactive Phosphorus	·015	mg/L P
Turbidity	35	N.T.U.
Dissolved Oxygen:		☐ mg/L ☐ %

Any Comments for Your Facilitator?

Another load of dumped (new)
rubbish.
Running well up abit on last
There is not many mistletoe
But there is birds

2 Maggies!!

Weather Conditions at Time of Sampling

☑ Sunny   ☐ Cloudy

☐ Overcast   ☐ Raining

☐ Windy

Last Rainfall

☐ More than a week ago   ☑ During the last week

☐ During the last 24 hours ☐ Raining Now

Amount of rain: mm

Water Appearance

☐ Clear   ☑ Muddy

☐ Milky   ☐ Foamy / Frothy

☐ Stained Green ☐ Stained Brown

☐ Smelly   ☐ Scummy

☐ Oily   ☐ Other:

Drains

Drain Flow:	☐ Drain flowing	☐ Drain not flowing