West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet						
Site Details T			Test Details			
Site Code: LAT021		Date: A	-4.2010,	\$		
Site Name: Latrobe River @ Scarnes Bridge Time:			1.45 AM	□ PM	RECEIVE	
Site Grid Reference Easting: Person(s			Conducting the Survey /	Test: Judy	0 6 APR 2010	
Northing: Name of N			Monitoring Group:		BY	
Your Meter - Readi (when in CAL Mode		oration	(after pressing	eading Post Calib the ENT button)	pration	
pH Meter in	pH Meter in	5: XDID	EC Meter pH Meter in	pH Meter in		
7.01	4.01		7.01	4,01		
Water Condition	n (Circle)		100 mm (100 mm) (100	41.00 A 41.00	addred to the	
Steady Flow	Rising	Peak	Falling	Stagnant (pools)	Dry (no water)	
	And the second				6. 21. 1. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2.	
Test Results				ts for Your Fa		
Air Temperature	10.0	°C	hate this	s she mossie	s, Avse op in	
Water Temperature	18.3	°C	I hate this mud/might to do with	nowe now	Something	
рН	7.4		And Hann	Lan nest of	COMMISSION	
Electrical Conductivity	200	Dus □ms	you would	like??	comments i am johno! where bucket	
Reactive Phosphorus	, DIS	mg/L P	Bruise on	shin from	were bucket	
Turbidity	32	N.T.U.	nit up on-	the joys of a	u Volunteer	
Dissolved Oxygen:		☐ mg/L ☐ %	1000100 10310	* s		
		1				
Weather Conditions at Time of Sampling			Water Appearance			
Sunny	☐ Cloud	у	☐ Clear	ML	ıddy	
☐ Overcast ☐ Raining		ng	☐ Milky	□Fo	amy / Frothy	
Windy			☐ Stained Gree	n □ Sta	ained Brown	
TECNOS MARIE EN MUNICIPAL DE CONSTRUCTION DE CONTROL DE CONTROL DE CONTROL DE CONTROL DE CONTROL DE CONTROL DE	Nepsile 2010 Million (UN Allendar)		☐ Smelly	□ Sc	ummy	
Last Rainfall			☐ Oily	□ Ot	her:	
☐ More than a week ago ☐ During the last week						
☐ During the last 24 hours ☐ Raining Now			Drains			

Post: West Gippsland Waterwatch Reply Paid 1374 Traralgon 3844 or Fax: 51757899

mm

Amount of rain:

Drain Flow:

□ Drain flowing

☐ Drain not flowing