

RECEIVED

06 FEB 2012

West Gippsland Waterwatch Volunteer Water Quality Monitoring Data Sheet

Site Details	
Site Code:	2 HWC 002
Site Name:	WETLANDS LAKE
Site Grid Reference	Easting:
	Northing:

Test Details	
Date:	22-1-12 + B-1-12
Time:	12:00 <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM
Person(s) Conducting the Survey / Test:	Peter Ref
Name of Monitoring Group:	KEY FIELD WETLANDS

Your Meter - Reading Before Calibration (when in CAL Mode)				Your Meter - Reading Post Calibration (after pressing the ENT button)			
EC Meter				EC Meter			
pH Meter in 7.01		pH Meter in 4.01		pH Meter in 7.01		pH Meter in 4.01	

Drains		
Drain Flow:	<input type="checkbox"/> Drain flowing	<input type="checkbox"/> Drain not flowing

Test Results		
Air Temperature	22.7	°C
Water Temperature	22	°C
pH	7.5	
Electrical Conductivity	2200	<input type="checkbox"/> µS <input type="checkbox"/> mS
Reactive Phosphorus	0.7	mg/L P
Turbidity	14	N.T.U.

31 FEB
v
7.5
2200
0.7
14

Any Comments for Your Facilitator?

Weather Conditions at Time of Sampling	
<input type="checkbox"/> Sunny	<input checked="" type="checkbox"/> Cloudy
<input type="checkbox"/> Overcast	<input type="checkbox"/> Raining
<input type="checkbox"/> Windy	

Water Appearance	
<input checked="" type="checkbox"/> Clear	<input type="checkbox"/> Muddy
<input type="checkbox"/> Milky	<input type="checkbox"/> Foamy / Frothy
<input type="checkbox"/> Stained Green	<input type="checkbox"/> Stained Brown
<input type="checkbox"/> Smelly	<input type="checkbox"/> Scummy
<input type="checkbox"/> Oily	<input type="checkbox"/> Other:

Last Rainfall	
<input type="checkbox"/> More than a week ago	<input type="checkbox"/> During the last week
<input type="checkbox"/> During the last 24 hours	<input type="checkbox"/> Raining Now
Amount of rain:	mm