



Physical & Chemical Tests Record Sheet
(To be completed monthly)

Site Name: BIG TREE		Site Code: CO-WTE050
Name of Monitoring Group: WYE RIVER WATERWATCH GROUP		
Person(s) Conducting the test: YVONNE SHEPPARD		
Date of test: 6/9/20		Time of test: 10:45 am pm
Site Risk Assessment Completed: <input type="checkbox"/> signature please: Site risk and management assessment at rear of book. Please note circumstantial hazards and additional risks in the box below		
Test	Result (units)	Calculations, dilutions and comments
Dissolved Oxygen	8.8 mg/L 80 % sat.	
Water Temperature	10 °C	
Air Temperature	15 °C	
pH	Meter calibrated to <input checked="" type="checkbox"/> pH 7 & <input checked="" type="checkbox"/> pH 10 7.4 pH units	
Electrical Conductivity (Salinity)	Meter calibrated to <input checked="" type="checkbox"/> 1413, <input type="checkbox"/> 2,000 or <input checked="" type="checkbox"/> 12,880EC 208 EC units μS/cm.	
Reactive Phosphorus	0.045 mg/L P	
Turbidity	1.83 N.T.U. /F.T.U.	
Weather conditions at the time of sampling: <input checked="" type="checkbox"/> sunny <input type="checkbox"/> cloudy <input type="checkbox"/> overcast <input type="checkbox"/> raining <input type="checkbox"/> windy		
Rainfall: Last rainfall: <input type="checkbox"/> More than week ago <input checked="" type="checkbox"/> During the last week <input type="checkbox"/> During the last 24 hours <input type="checkbox"/> Raining now Amount of rain (mm) _____		
Water flow Flow indicator (if available) _____ ML/day Estimate of flow <input type="checkbox"/> Not flowing (still) <input type="checkbox"/> Not flowing (pool) <input type="checkbox"/> Low (minimum) <input type="checkbox"/> Medium (average) <input checked="" type="checkbox"/> High (but below bankfull) <input type="checkbox"/> Flood (over bank) <input type="checkbox"/> Permanent (lakes & wetlands)		Water appearance <input type="checkbox"/> Clear <input type="checkbox"/> Milky <input type="checkbox"/> Foamy /frothy <input type="checkbox"/> Muddy <input type="checkbox"/> Smelly <input type="checkbox"/> Stained green <input type="checkbox"/> Scummy <input type="checkbox"/> Oily <input type="checkbox"/> Stained brown <input type="checkbox"/> Other (description) _____
Stream depth Depth indicator _____ m <input type="checkbox"/> 0 - 50 cm deep <input type="checkbox"/> 51cm-1m deep <input checked="" type="checkbox"/> 1 to 2 m deep <input type="checkbox"/> Unknown depth		
Stream width Average width of stream: _____ m <input type="checkbox"/> < 2 m wide <input checked="" type="checkbox"/> 2 to 5 m wide <input type="checkbox"/> >5 m wide		
Drain present at site: <input checked="" type="checkbox"/> no <input type="checkbox"/> yes Water flowing from drain: <input type="checkbox"/> yes Color _____ Odour _____		
Litter pollutants: (Tick type found) <input type="checkbox"/> paper <input type="checkbox"/> bottles <input type="checkbox"/> polystyrene <input type="checkbox"/> oil <input type="checkbox"/> petrol/diesel <input type="checkbox"/> packets <input type="checkbox"/> cans <input type="checkbox"/> waxed cardboard <input type="checkbox"/> other		
Circumstantial hazards and additional risks Hazard: FALLEN TREE ACROSS PATH Risk: MEDIUM		Waterwatch Data Management System: Data entry Person entering site visit information Date of entry Site visit approved by Coordinator (initial and date)
Risk Control Measures: CARE WALKST NEGOTIATING		