

Waterwatch Results: Friends of Dandenong Valley Parklands
 Dandenong Creek and Jells Lake Landing

Test Completed Date 25/6/21

Tests completed by Christine Dix, David Lumb, Emily Theng,
 Gus Romero, Samuel Dryanto, Bryan

Test Site	Calibration *	Dandenong Creek Bridge site (DDN 050)	Jells Lake Landing (ME DJE 200)
Time:		10:13 AM	10:30 AM
Ammonium mg/l		0.0	0.0
D.O (Dissolved oxygen concentration)		7.2 66-45%	8.8
Water Temperature		11.7 °C	11.5 °C
Air Temperature		12.1 °C	11.9 °C
*pH (Acidity/alkalinity)	*	7.2	6.6
*Electrical Conductivity	*	470	190
Reactive Phosphate (Nutrient levels)	0-10	0-10	0-03
Turbidity		40	10

Site Descriptions	Dandenong Creek Bridge site (DDN 050)	Jells Lake Landing (ME DJE 200)
Weather (Sunny, cloudy, overcast, raining, windy)	overcast	overcast
Rainfall (More than a week ago, during last week, during last 24 hours, raining now)	during last 24 hours	
Amount of rainfall		2 mm
Water flow (Flood, Medium, Low)	medium	NA
Water appearance (Clear, muddy, milky, other)	muddy	muddy
Stream depth (0-50cm, 51-99cm, 1-2m, >2m)	0-50 cm	0-50 cm
Stream width (<2m, 2m-5m, >5m)	>5m	NA
Litter/pollutants (bottles, plastic, packets, waxed cardboard, cans, polystyrene, paper, clothing)	plastic, styrofoam, plastic bottle	no

Comments:

.....

.....

.....

.....