


Waterwatch Results: Friends of Dandenong Valley Parklands Dandenong Creek and Blind Creek

Tests completed by: *David, Christine*

Test Completed	Dandenong Creek Bridge site (DDN 050)	Blind Creek (DBC 250) <i>Jells Lake</i>
Date:		
Time:	10.10	10.25
Ammonium mg/l	^{10.42} 0.00	^{11.15} 0.00
D.O mg/L (Dissolved oxygen concentration)	8.0 71.68%	8.8
Electrical μ S/cm Conductivity	590.	210
pH (Acidity/alkalinity)	6.9	7.1
Reactive PO ₄ Phosphate mg/L (Nutrient levels)	^{10.46} 0.07	^{11.02} 0.03
Air Temperature °C	14.9	10.7 14.3
Water °C Temperature	10.4	10.7
Turbidity NTU	28	17

Site Descriptions	Dandenong Creek Bridge site (DDN 050)	Blind Creek (DBC 250) <i>Jells Lake</i>
Weather (Sunny, cloudy, overcast, raining, windy)	Sunny	ditto
Rainfall (More than a week, during last week, last 24 hours, raining now)	last week 8mm	"
Amount of rainfall		
Water flow (Flood, Medium, Low)	med. 	"
Water appearance (Clear, muddy, milky, other)	muddy	"
Stream depth (0-50cm, 51-100cm, 1-2m, >2m)	51-100.	
Stream width (3-5m, >5m)	>5m	
Litter/pollutants	polystyrene, plastic	