

# Waterwatch Results: Dandenong Creek and Jells Lake

Test Completed Date: 1/6/23

Tests completed by: Christine Dix, John Dix

Test Site	Calibration *	Dandenong Creek Bridge site (DDN 050)	Jells Lake Landing (ME_DJE 200)
Time:		11:45	12:00
Ammonium mg/l		0.20	0.00.
D.O (Dissolved oxygen concentration)		7.8, 78.61%	7.0
Water Temperature		15.7	14.9
Air Temperature		14.3	15.8
*pH (Acidity/alkalinity)	*	7.5	7.1
*Electrical Conductivity	*	380	<del>240</del> 210
Reactive Phosphate (Nutrient levels)		0.07	0.15
Turbidity		30	15
<b>Site Descriptions</b>			
Weather (Sunny, cloudy, overcast, raining, windy)		sunny	sunny.
Rainfall (More than a week ago, during last week, during last 24 hours, raining now)		last 24 hrs 5.5mm	last 24 hours
Amount of rainfall		5.5	5.5
Water flow (Flood, Medium, Low)		Med.	N/A
Water appearance (Clear, muddy, milky, other)		Clear Muddy.	clear
Stream depth (0-50cm, 51-99cm, 1-2m, >2m)		<del>0-50cm</del> 51-1m	0-50
Stream width (<2m, 2m-5m, >5m)		>5m	N/A
Litter/pollutants (bottles, plastic, packets, waxed cardboard, cans, polystyrene, paper, clothing)		Nil!	Nil

Comments:

.....

.....