

## West Gippsland Waterwatch Volunteer Water-Quality Monitoring Data Sheet

| Site Details<br>Site Code: HAZ015   |                     | Site Name: Hazel Ck / King st WARRAGUL                         |             |                                  |            |   |                        |                              |  |
|---|---------------------|--|-------------|----------------------------------|------------|---|------------------------|------------------------------|--|
| Site Grid Reference   |                     | Easting: 405298  |             |                                  |            | Northing: 5774710   |                        |                              |  |
| Test Details  Date: 22-6-2023  Time: 1.0 An   |                     | Person(s) Conducting the Test: Name of Monitoring Group: "Frie |             |                                  |            | 1. NICK VANDEN BERGH NICK 2. JOHN GOOSHAN- JOHN ends of Land and Water" |                        |                              |  |
| Preparation   |                     |  |             |                                  |            |   |                        |                              |  |
| * pH meter conditioned: Y/N  " " calibrated: Y/N  |                     |  |             | <u>EC</u>                        | meter<br>" | conditioned:<br>calibrated:   |                        | (circle one)<br>(circle one) |  |
| Test Results  |                     |  |             |                                  | ( )        |   |                        | 0.1                          |  |
| Water Temp.: 4'+°C Air Temp.: 16, 3°C pH value: 6 6. Elec. Conduct.: 22 μS  |                     |  |             |                                  |            |   |                        |                              |  |
| Reactive Phosphorus: O  | ,015                | mg/L (P)   |             | T                                | urbidity:  | N   | ITU 15                 |                              |  |
| Weather Conditions at Time  |                     | lease tick   |             |                                  | -          | 7.5   |                        |                              |  |
| Sunny   | Cloudy              |  | ☐ Overcast  |                                  | L          | Raining   | ☐ Windy                |                              |  |
| Last Rainfall (please tick) ☐ More than a week ago  | During the la       | st week  | ☐ During th | e last 24 h                      | rs [       | ☐ Raining Now   | Amount o               | frain:50 mm                  |  |
|   |                     |  |             |                                  |            |   |                        |                              |  |
| Water Flow: (please tick)  ☑ Bank-full - High flow within channel capacity, and in-stream habitats connected  ☐ High - Less than bank-full, and in-stream habitats connected  ☐ Medium - Flow is normal / typical average flow  ☐ Low - Minimum flow in channel/ continuous flow in some part of channel (in-stream habitat connected)  ☐ Dry - No continuous flow in channel and no pools  ☐ Pools - No continuous flow in channel and intermittent pools (in-stream habitats not connected) |                     |  |             |                                  |            |   |                        |                              |  |
| Water Appearance (please to   |                     |  |             |                                  |            |   |                        | _                            |  |
| ☑ Clear<br>☐ Muddy  | ☐ Scummy<br>☐ Milky | ny ☐ Smelly<br>☐ Oily  |             | ☐ Foamy / Frothy ☐ Stained Green |            |   | ☐ Stained Brown Other: |                              |  |
| Stream Depth and Width (pl<br>Depth: 0-50cm +<br>Width: 2-5m  |                     | W-   |             |                                  |            |   |                        |                              |  |
|   |                     |  |             |                                  |            |   |                        |                              |  |
| Circumstantial Hazards and Additional Risks   |                     |  |             |                                  |            |   |                        |                              |  |
| Hazard:<br>Risk Control Measures:   |                     |  | Risk:       |                                  |            |   |                        | _                            |  |
| 8   |                     |  |             |                                  |            |   |                        |                              |  |
| Comment: Key in data, and store the form in our local files in case of later query. (No requirement to post to Traralgon.)  |                     |  |             |                                  |            |   |                        |                              |  |

Conditioning times: pH meter: 2 to 3 hours; EC meter: 10 mins.

Local Data Sheet



T: 1300 094 262 F: (03) 5175 7899 E: westgippy@wgcma.vic.gov.au www.wacma.vic.gov.au